

FORScan v2.3.66 release, Ford Ranger/Courier/Mazda B-Series EcoBoost Gasoline Turbocharged Direct Injection 2.3L 2019 (2019 MY), VIN: 1FT*****14272

DTC

Module	Code	Code: C1001 - Vision System Camera
PCM	None	Additional Fault Symptom (:97): - Component Or System Operation Obstructed Or Blocked Status (-68): - Previously Set DTC - Not Present at Time of Request - Malfunction Indicator Lamp is Off for this DTC - Test not complete Module: Image Processing Module A Freeze Frame #1: -EVENT_TIME: 210629687 s (Mon Nov 17 13:19:01 2025) - Event time -TOTAL_DISTANCE: 26308 miles - Total Distance -MODULE_VOLTAGE: 14.8 V - Control Module Voltage -OUTDOOR_TEMPERATURE: 44 °F - Outside temperature -VEHICLE_SPEED: 34 mph - Vehicle Speed -ECU_POWER_SUPPLY: 14.6 V - ECU Power Supply Voltage -ECU_INTERNAL_TEMPERATURE: 73 °F - ECU Internal Temperature
OBDII	None	
APIM	None	
DCDC	None	
PAM	None	
BdyCM	B11DB:08-08	
BECMB	None	
SODR	None	
SODL	None	
FCIM	B10B8:63-08	
ATCM	None	
TRM	None	
DSP	None	
OCS	None	
C-CM	None	
ABS	U2107:00-08	
TCU	None	
RTM	None	
RCM	None	
PSCM	None	
ACM	None	
SCCM	None	
IPC	None	
GWM	None	
IPMA	C1001:97-68	
IPMA	U0418:86-28	

Interface: Vehicle: Ready 12.1V

Windows taskbar: 5:18 PM 12/4/2025

C1001:97	Vision System Camera: Component or System Operation Obstructed or Blocked	CLEAN and INSPECT the windshield in front of the camera, remove any aftermarket stickers that may be blocking the view of the camera. REPAIR or REPLACE the windshield as necessary if damage is found.
----------	---	---