

JOHN BLANKENHORN 816 SUNCREST PLACE SOUTH CHARLESTON, WV 25303 jblankenhorn@gmail.com		VEHICLE ID 1FTER4FH5LLA28993	MILES IN 60143	MILES OUT 60144	DATE/TIME IN 01/05/24 09:18	DATE OUT 01/08/24	INVOICE NO. 23765
VEHICLE DESCRIPTION 2020 FORD RANGER SUP					TAG NO. 00597	STATUS COMPLETE	
CONTROL NO. 236072	LICENSE PLATE NO. 02R973	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS Cash
HOME (740) 707-9048	CELL (304) 400-2403	PHONE 3	STOCK NO.	SERV. ADV. CODY STARCHER (614)		RO COMMENT	

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
F +	Continued					
Line Total...						\$71.30

Authorized Estimates					
Date/Time	Amount	Authorized By	Authorization Method	Phone/Email	
01/05/2024 09:18	\$31.94		Initial Estimate		

Warranty Claim Type: F Authorization Code: Service Cont No:

Totals	
	Amount
Labor	\$872.37
Parts	\$1,396.88
SalesTax	\$144.66
Disc.Labor	-\$87.24
Disc.Parts	-\$142.38
Misc.Chg	\$6.00
Misc.Tax.	\$8.00
Parts-Other	\$26.88
Total Amount Due	\$2,225.17
Ford Pass	\$223.32
CTRL#FORDPASS	---
Amount Due	\$2,001.85

***** Thank You For Choosing Todd Judy Ford *****

You may receive a customer satisfaction survey from Ford Motor Company regarding this service visit. If for any reason you cannot grade us as "Completely Satisfied", please contact the Service Manager Mark Puher immediately! You being completely satisfied and rating us as a "5 Star" Service Center is our # 1 goal.

Thank you, Todd Judy Ford Service Team

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

On behalf of servicing dealer, I hereby certify that the information contained hereon is accurate unless otherwise shown. Warranty services described were performed at no charge to owner. There was no indication from the appearance of the vehicle or otherwise, that any part repaired or replaced under this claim had been connected in any way with any accident, negligence, or misuse. Records supporting this claim are available for (1) year from the date of payment notification at the servicing dealer for inspection by manufacturer's representative.

JOHN BLANKENHORN 816 SUNCREST PLACE SOUTH CHARLESTON, WV 25303 jblankenhorn@gmail.com		VEHICLE ID 1FTR4FH5LLA28993	MILES IN 60143	MILES OUT 60144	DATE/TIME IN 01/05/24 09:18	DATE OUT 01/08/24	INVOICE NO. 23765
VEHICLE DESCRIPTION 2020 FORD RANGER SUP					TAG NO. 00597	STATUS COMPLETE	
CONTROL NO. 236072	LICENSE PLATE NO. 02R973	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS Cash
HOME (740) 707-9048	CELL (304) 400-2403	PHONE 3	STOCK NO.	SERV. ADV. CODY STARCHER (614)		RO COMMENT	
Line	Op-Code	Fail Code	Tech	Hours	Type	Amount	
C *	Continued						
Correction test drove vehicle was able to hear noise after the axle replacment replaced axles instructed customer to drive vehicle and see if the noise gets worse							
						Line Total...	\$135.00
D +	TIRE2A		A08		Customer		\$144.93
Concern CUSTOMER STATES MOUNT AND BALANCE 2 TIRES AND PERFORM WHEEL ALIGNMENT							
Correction replaced 2 tires and completed aalignment							
Part Number		Description		Qty.	Unit Price	Ext. Price	
9004 78163		255/65R17		2	\$247.00	\$494.00	
A,WEIGHT		WHLWGT WEIGHT		2	\$3.45	\$6.90	
						Parts Total...	\$500.90
Misc. Code		Description		Qty.	Unit Price	Ext. Price	
		TIRE DISPOSAL FEE		2.0	\$4.00	\$8.00	
						Misc Total...	\$8.00
						Line Total...	\$653.83
E +			A08		Customer		\$540.00
Concern tech states bothrear axle seals are leaking							
Correction replaced both rear axles test drove ok at this time							
Part Number		Description		Qty.	Unit Price	Ext. Price	
XY 80W90 QL		OIL - REAR AXLE		2	\$12.78	\$25.56	
KB3Z 4234 D		SHAFT ASY - RE		2	\$403.00	\$806.00	
						Parts Total...	\$831.56
						Line Total...	\$1,371.56
F +	WIPERS		A08		Customer		\$15.00
Concern CUSTOMER REQUESTS REPLACEMENT OF WIPER BLADES							
Correction REPLACED WIPER BLADES							
Part Number		Description		Qty.	Unit Price	Ext. Price	
KB3Z 17528 BA		BLADE ASY - WI		1	\$28.15	\$28.15	
KB3Z 17528 CA		BLADE ASY - WI		1	\$28.15	\$28.15	
						Parts Total...	\$56.30