

AIR.

722162 WF

PC: PART#: COUNT:

CLAIM TYPE:

AUTH CODE:

722162

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A:

35551 VERIFIED CUSTOMER CONCERN, A/C BLOWING HOT AIR, VISUAL CHECK  
WHEN A/C ON, COMPRESSOR WORKS FAN WORKS, THERE IS NO LEAKS, LOG IN TO  
FDRS, CHECK FOR DTCs, FOUND B1082, Right Temperature Damper Motor,  
THERE IS A SSM 51313 Climate Control Temperature Will Not Adjust This  
may be due to an issue with the blend door and its controls, replace  
the air distribution housing/heater assembly. Repair (Parts & Labor) US  
Dollar customer part \$1,242.02 Ford to cover \$1,863.00 MSPA644250 Approved

\*\*\*\*\*