

Eliminated Features for 5G North American Ranger

Model Year	2019			2020			2021			2022		
	XL	XLT	Lariat	XL	XLT	Lariat	XL	XLT	Lariat	XL	XLT	Lariat
Trim												
Feature Removal	Baseline											
Removed Forward Sensing as standard. Available in Tech Pkg	-	-	-		X			X			X	
Removed Forward and Reverse Sensing as standard in Copilot 360 pkg. Reverse sensing available separately	-	-	-	X			X			X		
Removed Forward Sensing as standard in 500a	-	-	-						X			X
Removed Engine Cover	-	-	-	X	X		X	X	X	X	X	X
Removed Rear Seat folding headrest	-	-	-	X	X	X	X	X	X	X	X	X
Removed Glovebox manual pocket	-	-	-	X	X	X	X	X	X	X	X	X
Removed Glovebox damper	-	-	-	X	X	X	X	X	X	X	X	X
Removed Front Seat folding headrest	-	-	-				X	X	X	X	X	X
Removed hood struts	-	-	-							X	X	X
Removed Glovebox light	-	-	-									X
Removed Windshield wiper deicer	-	-	-						X			X
Removed Universal Garage Door Opener on 500a	-	-	-									X
Removed Power Folding Side Mirrors on 301a	-	-	-					X			X	
Removed Power Folding Side Mirrors on 302a	-	-	-								X	
Removed Console tray	-	-	-	X	X	X	X	X	X	X	X	X
Removed mid tiedowns in bed	-	-	-	X	X	X	X	X	X	X	X	X
Removed ECOboost badge	-	-	-	X	X	X	X	X	X	X	X	X
Removed PRNDS lamp	-	-	-	X	X	X	X	X	X	X	X	X
Removed Tailgate key lock	-	-	-							X	X	X
Removed 12V outlet in console without 110V option	-	-	-							X	X	
Removed Rocker Panel Plugs	-	-	-							X	X	X
Removed Chrome trim on parking brake button	-	-	-							X	X	X
Removed chrome trim on 12V outlets	-	-	-							X	X	X
Removed color keyed Tailgate handle	-	-	-									X
Changed Front Fenders from Aluminum to Steel	-	-	-				X	X	X	X	X	X
Changed Spindles from Aluminum to steel	-	-	-				X	X	X	X	X	X
Removed touch lock from rear passenger doors	-	-	-									X
Removed Owners manual cover	-	-	-				X	X	X	X	X	X
Removed Tow Hooks on 4x2 XLT & Lariat. Available in FX2 Pkg	-	-	-					X	X		X	X
Removed 110V Power outlet as standard on XLT. Available in 301a and 302a.	-	-	-					X			X	
(2) 4.2" productivity screens instrument cluster replaced with (1) 4.2" screen on 500A	-	-	-									X
Removed cupholder rubber insert	-	-	-							X	X	X
Removed console storage rubber insert	-	-	-							X	X	X
Removed floor mat mounting tabs on passenger side	-	-	-	X	X	X	X	X	X	X	X	X
Removed Auto Start/Stop feature (\$50 Credit)	-	-	-							X	X	X
Removed LED Headlights from Lariat trim (\$500 Credit)	-	-	-									X
<b>Added Packages/Features:</b>												
Added FX2 Package				X	X	X	X	X	X	X	X	X
Added Black Package					X	X		X	X		X	X
Added Special Edition Package							X			X		
Added Splash Package											X	X
Added Heated Mirrors to 302a											X	
Added Color Key bezel to external keypad accessory										X	X	X